Bulletin No.:

Date: 4-19-88



SERVICE/PARTS

Subject:

Covers Over the Main Drive Shaft Clutches

Models:


3000 through 4100


Covers can be installed over the main drive shaft clutches to improve water tightness.

Parts needed:

- 1 94388-2 Guard
- 1 94389-2 Guard
- 2 140984-2 Gasket

Covers will not fit on machines equipped with a clutch cooling system (blower).





SECTION 8-8"